



APPENDIX A
Rural Road Safety Audit Photographs




Photograph A1 Mixture of warning signs provides confusing message to approaching motorists.



Photograph A2 Poorly located chevron sight board. Should be mounted in line with the centre of approaching traffic lane.




Photograph A3 Poorly located bridge end marker posts which do not define the narrowest part of the bridge deck width.



Photograph A4 Raised concrete sump creating an unnecessary roadside safety hazard to errant vehicles.



Photograph A5 Poor intersection layout due to low angle of entry. Note how the Give Way sign located on the side road is visible from the main road.



Photograph A6 Good use of a chevron sight board to improve the conspicuity of an intersection to approaching traffic.